

Accessories

Extensive, user-friendly Range



MW 1100 / MW 1100S:

- Belt bag
- Charger lead for operation in vehicles

MW 1150:

- Thermoprinter P 1150
- Pt100 temperature sensor
- External infrared temperature sensor
- Connector kit for analog output 4-20 mA
- Hoppers, brushes, dishes
- Spare beakers for beaker sensors

